

EZ Pipe Manifold Update

May 2024

The EZ Pipe Primary/Secondary Manifolds have recently been updated for easier installation and servicing. The part number of updated EZ Pipe Manifolds ends with “C” for easy identification.

251-063C: SFC 99-1, SFC 125-1, SFB 99-1, SFB 120-1, HC Series, DC Series

251-064C: SFC 160-1, SFC 199-1

Updated EZ Pipe Manifolds include the following improvements:

- Revised boiler connections allow the nuts to fall out of the way for easy gasket replacement.
- The boiler return pipe has been revised to provide better compatibility with a wider range of Tankless Water Heater service valves.
- The $\frac{3}{4}$ " x 1" bushings which are no longer required on updated Superflow units with 1" space heating connections have been removed.



EZ Pipe Manifold version C with typical tankless water heater service valves